



See Note 4

NO SCALE

ES-15C

1. Type 4 conduit shall be secured to the nearest walkway bracket using one-hole galvanized malleable iron or steel straps and brass machine screws tapped into the bracket.
2. See Overhead Signs Standard Plans for overhead signs and frame juncture details for photoelectric unit installation.
3. Enclosures and straps shall be secured by $\frac{3}{8}$ " maximum size screws.
4. The Contactor and test switch enclosures shall be readily accessible from the sign walkway.